

Annexure D

BUILDING SAFETY CERTIFICATE

No. 2758

Dated: 26/4/24

It is certified that the existing building Gurukul Pundri (name of the building or premises) at Dhand Road Fatehpur Pundri (Kaithal) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3	G+3	G+2	G		

The building is owned/occupied by Gurukul Pundri Distt. Kaithal (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (B & R) (Name of Department/ Govt.) on 24/04/24 (date of inspection) in the presence of Vijay Kumar (J.E.) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 26/4/24 for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 26/04/2024 at Kaithal by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Executive Engineer
Provincial Division No-II
PWD B&R, Kaithal

Name: _____

Designation : _____

Name & Address of Department/ Office: _____